

Full Inspection Report

Inspection Date: 12-31-2025

Reconditioning info

Total Reconditioning Cost	Details
\$1,636.42	This is the amount of money we invested in this vehicle to assure the vehicle operates safely and meets minimum certification standards for performance. View Details

Inspected By

Name	Organization
Andrew Cooper	Beaver Toyota

Vehicle Information Summary

VIN	Year	Make	Model	Odometer
5YJYGAE8MF179615	2021	Tesla	Model Y	57,926

EV Components

Question	Status	Comment	Repair/Replace
----------	--------	---------	----------------

VIN and Dealer Code Check

Question	Status	Comment	Repair/Replace
Run and print Vehicle History Report and attach	Checked and OK	-	-
Run a Techstream Health Check and retain the diagnostic report in dealer file	Checked and OK	-	-
Check for and perform outstanding Recalls and applicable SSCs	Checked and OK	-	-

Road Test_EV

Question	Status	Comment	Repair/Replace
Category Comment REPLACED FRONT WIPER BLADES PEFORMED ALIGNEMNT			

Frame, Structure and Underbody_EV

Question	Status	Comment	Repair/Replace
Category Comment REPLACED ALL 4 TIRES			

Under Hood_EV

Question	Status	Comment	Repair/Replace
----------	--------	---------	----------------

Functional and Walkaround_EV

Question	Status	Comment	Repair/Replace
----------	--------	---------	----------------

Exterior Appearance

Question	Status	Comment	Repair/Replace
Body surface condition	Checked and OK	-	-
Exterior is washed, clean and free of water spots	Checked and OK	-	-
Paint is free of swirl marks and has an even, high luster	Checked and OK	-	-
Paint is free of removable scratches	Checked and OK	-	-
Paint is free of wax residue	Checked and OK	-	-
Wheels/wheel covers are clean	Checked and OK	-	-
Wheel wells are clean	Checked and OK	-	-
Tires are clean and properly dressed	Checked and OK	-	-

Engine Compartment

Question	Status	Comment	Repair/Replace
Compartment is clean	Checked and OK	-	-
Under-hood heat insulator pad is clean	Checked and OK	-	-
Engine and compartment are	Checked and OK	-	-

properly dressed

Interior Appearance

Question	Status	Comment	Repair/Replace
Interior is free of debris	Checked and OK	-	-
Dash and vents are clean and properly dressed	Checked and OK	-	-
All crevices are clean	Checked and OK	-	-
Ashtrays and lighter are clean (if equipped)	Checked and OK	-	-
Door jambs are clean	Checked and OK	-	-
Glove box and console compartments are clean	Checked and OK	-	-
Cabin air filter condition	Checked and OK	-	-
Seats, carpets, floor mats (if equipped) and headliner are free of stains	Checked and OK	-	-
Free of odor, including heavy fragrance	Checked and OK	-	-
Glass is clean and free of streaks	Checked and OK	-	-
No evidence of previous improper interior repairs	Checked and OK	-	-

Exterior Repairs

Question	Status	Comment	Repair/Replace
Body is free of all dents	Checked and OK	-	-
Body is reasonably free of dings	Checked and OK	-	-
Paint is reasonably free of scratches and chips	Checked and OK	-	-
Vehicle is free of improper paint repairs or mismatched color	Checked and OK	-	-
Glass is free of improper repairs	Checked and OK	-	-
Bumpers are free of cuts, gouges and mismatched paint	Checked and OK	-	-

Interior Repairs

Question	Status	Comment	Repair/Replace
Interior leather, vinyl, plastic, carpet and fabric surfaces are	Checked and OK	-	-

free of holes, rips, tears,
excessive wear or fading

Additional Inspection Items_EV

Question

Status

Comment

Repair/Replace