

Full Inspection Report

Inspection Date: 04-15-2026

Inspected By

Name	Organization
Kenneth Broyles	Beaver Toyota

Vehicle Information Summary

VIN	Year	Make	Model	Odometer
5TDAAAA56SS024398	2025	Toyota	Grand Highlander	22,871

VIN and Dealer Code Check

Question	Status	Comment	Repair/Replace
Run and print Vehicle History Report and attach	-	-	-
Run a Techstream Health Check and retain the diagnostic report in dealer file	-	-	-
Check for and perform outstanding Recalls and applicable SSCs	-	-	-

Road Test

Question	Status	Comment	Repair/Replace
Cold engine operation performs properly	-	-	-
Throttle operates properly during cold start	-	-	-
Vehicle operates properly during warm-up conditions	-	-	-
Engine performs properly during operating temperature	-	-	-
Engine reaches normal operating	-	-	-

temperature		
Engine fan(s) operate properly	-	-
Brake pedal free play and travel within specifications	-	-
No abnormal vibrations and noises during brake applications	-	-
ABS operates properly (via Techstream Health Check)	-	-
Parking brake operates properly and within specification	-	-
Seat belt material condition	-	-
Seat belts operate properly with full extension and smooth operation	-	-
Transmission/clutch operates smoothly	-	-
Automatic transmission operates properly during cold temperature	-	-
Automatic transmission operates properly during operating temperature	-	-
Steering has normal feel in lock-to-lock turning	-	-
Steering wheel centered in straight-line driving	-	-
Vehicle tracks and drives straight on level surface	PREFORM 4 WHEEL ALIGNMENT	☑ Repaired
Tilt and telescopic steering mechanism operates properly	-	-
Front windshield wiper operates properly in all modes	-	-
Rear windshield wiper operates properly in all modes	-	-
Windshield washer fluid sprays properly	-	-
Wiper blades clear glass properly	FRONT AND REAR WIPEERS REPLACED	☑ Replaced
Wipers return to correct position when off	-	-
Speedometer functions properly	-	-
Odometer application registers mileage in every mode	-	-
Cruise control operates properly	-	-
Heater operates properly	-	-
A/C operates properly	-	-

No abnormal noise or vibration from engine	-	-
No excessive wind or road noise	-	-
No abnormal tire vibration/steering wheel shimmy during road test	-	-
No abnormal squeaks/rattles within the interior of the vehicle	-	-

Frame, Structure and Underbody

Question	Status	Comment	Repair/Replace
Frame/Unibody condition		-	-
Panel alignment and fit		-	-
Lower body and underbody condition		-	-
Suspension-related items for wear/leaks and proper performance		RF STRUT REPLACED	☑ Replaced
Inspect struts/shocks for leaks and wear		-	-
Power steering system operates properly with no leaks		-	-
Wheel covers secure and reasonably free of damage	N/A	-	-
Tires are inflated to specification and free of defects and damage		-	-
Minimum of 5/32" tread depth remaining across tread width		2 TIRES REPLACED	☑ Replaced
All four tires must be of same brand, model, size, tread design, speed and load rating		-	-
Brake calipers and lines operate properly with no signs of damage		-	-
The brake system contains all needed equipment (shim kit, pins, rattle clips, etc.)		-	-
Brake pad/shoe linings have a minimum thickness of 50% remaining		-	-
Brake rotors/drums within specifications with no abnormal grooving and discoloration		FRONT AND REAR ROTORS REPLACED	☑ Replaced
Exhaust system is properly secured with no leaks		-	-
Engine/transmission mounts operate properly with no signs of		-	-

wear			
Drive/axle shafts operate properly with no damage		-	-
CV joints/boots operate properly with no signs of wear		-	-
Inspect engine for fuel, oil, coolant or other fluid leaks		-	-
Inspect transmission case and pan for leaks		-	-
Differential fluid level correct with no leaks	N/A	-	-

Emissions and State Inspection

Question	Status	Comment	Repair/Replace
Perform emissions test and/or state inspection, if required	N/A	-	-

Under Hood

Question	Status	Comment	Repair/Replace
Drive belts and hoses free of cracks and damage		-	-
Confirm under-hood labels and decals		-	-
Air filter in good condition		AIRFILTER REPLACED	☑ Replaced
Battery has no visible damage		-	-
Perform battery check with Midtronics GR8		-	-
Battery posts and cables free of corrosion and damage		-	-
Battery properly sized and secure		-	-
Charging system operating properly and within specification		-	-
Engine coolant level within specification		-	-
Coolant specific gravity to -31° Fahrenheit		-	-
Change engine oil and filter		-	-
Check for evidence of oil gel		-	-
Oil, brake, clutch, transmission, transfer case, power steering and washer fluid at proper levels		-	-

Under-hood fluids clear and uncontaminated

-

Functional and Walkaround

Question	Status	Comment	Repair/Replace
Owner's Manual and TCUV Warranty Supplement in dealer's possession		-	-
Fuel gauge operational		-	-
Battery voltage gauge operational	N/A	-	-
Engine temperature gauge operational		-	-
Horn operates properly		-	-
Airbag(s) present with no evidence of deployment		-	-
Headlights are properly aligned		-	-
High and low beams operate properly		-	-
Tail lights operate properly		-	-
Brake lights operate properly		-	-
Side marker lights operate properly		-	-
Backup lights operate properly		-	-
License plate lights operate properly		-	-
No cracked or broken lenses of exterior lights		-	-
Instrument panel/warning lights operate properly		-	-
HVAC panel/lights operate properly		-	-
Instrument panel light dimmer operates properly		-	-
Turn signals operate properly and self-cancel		-	-
Rear-view interior mirror operates properly		-	-
Exterior mirrors' operation and condition		-	-
Remote mirror control operates properly		-	-

Glass free of cracks, stars and large chips	-	-
Window tinting clear and conforms to local requirements	-	-
Dome/courtesy lights operate with door cycles	-	-
Windows operate properly	-	-
Window locks operate properly	-	-
Power windows operate from master switch and all door switches	-	-
Audio/Cassette/CD/Aux system working properly; CD cartridge present (if equipped)	-	-
Audio speakers do not rattle at high volume and function properly	-	-
Antenna is present and functional	-	-
Clock operates properly	-	-
12v ACC power outlet operates properly	-	-
Ashtrays (if equipped) are present and operate properly	N/A	-
Headliner, sun visors, dash pad, upholstery, console, cup holders, trim panels and carpet are in place, in good condition and operate properly	-	-
Driver floor mat (if equipped) is appropriate floor mat for the vehicle, properly secured and not stacked on top of another floor mat	REPLACED FLOOR MATS	☑ Replaced
Doors open and close properly	-	-
Door locks, including child safety locks, operate properly	-	-
Remote keyless entry system and smart key system operate properly	ONE SMART KEY PROGRAMMED	☑ Replaced
Master key is present	-	-
Theft deterrent system operates properly	-	-
Seat adjustments and seat heater(s) operate properly	-	-
Memory seat control operates properly	-	-
Headrests function properly	-	-

Defogger indicator light operates properly		-	-
Rear defogger operates properly		-	-
Luggage compartment light operation and trim appearance		-	-
Luggage compartment is clean, free of debris, no stains		-	-
Hood and luggage compartment latches operate properly		-	-
Interior remote luggage compartment release operates properly		-	-
Emergency trunk release operates properly		-	-
Fuel door release operates properly		-	-
Spare tire's cover appearance and condition		-	-
Spare tire present		-	-
Spare tire has correct air pressure and a minimum of 5/32" tread remaining		-	-
No signs of damage to spare tire		-	-
Spare tire and storage areas are clean		-	-
Spare tire is securely fastened		-	-
Jack and tools are correct, present and secured		-	-
Acceptable aftermarket items checked	N/A	-	-
Removal of unacceptable aftermarket items	N/A	-	-

Exterior Appearance

Question	Status	Comment	Repair/Replace
Body surface condition		-	-
Exterior is washed, clean and free of water spots		-	-
Paint is free of swirl marks and has an even, high luster		-	-
Paint is free of removable scratches		-	-
Paint is free of wax residue		-	-

Wheels/wheel covers are clean	-	-
Wheel wells are clean	-	-
Tires are clean and properly dressed	-	-

Engine Compartment

Question	Status	Comment	Repair/Replace
Compartment is clean		-	-
Under-hood heat insulator pad is clean		-	-
Engine and compartment are properly dressed		-	-

Interior Appearance

Question	Status	Comment	Repair/Replace
Interior is free of debris		-	-
Dash and vents are clean and properly dressed		-	-
All crevices are clean		-	-
Ashtrays and lighter are clean (if equipped)	N/A	-	-
Door jambs are clean		-	-
Glove box and console compartments are clean		-	-
Cabin air filter condition		CABIN FILTER REPLACED	☑ Replaced
Seats, carpets, floor mats (if equipped) and headliner are free of stains		-	-
Free of odor, including heavy fragrance		-	-
Glass is clean and free of streaks		-	-
No evidence of previous improper interior repairs		-	-

Exterior Repairs

Question	Status	Comment	Repair/Replace
Body is free of all dents		-	-
Body is reasonably free of dings		-	-

Paint is reasonably free of scratches and chips	-	-
Vehicle is free of improper paint repairs or mismatched color	-	-
Glass is free of improper repairs	-	-
Bumpers are free of cuts, gouges and mismatched paint	-	-

Interior Repairs

Question	Status	Comment	Repair/Replace
Interior leather, vinyl, plastic, carpet and fabric surfaces are free of holes, rips, tears, excessive wear or fading		-	-

Additional Inspection Items

Question	Status	Comment	Repair/Replace
"Fade-away" dome light operates properly		-	-
Sunroof/convertible top operates properly through full range of positions		-	-
Convertible top lockout function operates properly	N/A	-	-
Radio security codes cleared	N/A	-	-
Navigation system operates properly and memory system cleared		-	-
Transfer case smoothly switches from 2WD to 4WD and back from 4WD to 2WD	N/A	-	-
Truck bed is in good condition	N/A	-	-
Truck bed-liner is in good condition and secured	N/A	-	-
Tailgate operates properly	N/A	-	-
Backup camera operates properly		-	-
Bluetooth® searches for signal		-	-
SOS (Safety Connect) light illuminates green		-	-
Lane Keep Assist operates properly		-	-
Dynamic Radar Cruise Control/Pre-Collision Systems		-	-

operate properly

Intelligent Parking Assist
operates properly

N/A

-

-

Hybrid Components

Question	Status	Comment	Repair/Replace
Hybrid battery	N/A	-	-
Battery control module (battery voltage sensor)	N/A	-	-
Hybrid power management control module	N/A	-	-
Electric motor/generator operates properly	N/A	-	-
ECVT operates smoothly and properly	N/A	-	-
Power inverter operates properly	N/A	-	-
Inverter coolant level	N/A	-	-
EV/Eco/Power modes operate properly	N/A	-	-
Check transaxle "park" mechanism	N/A	-	-
Multi-information display operates properly	N/A	-	-
Touch Tracer display operates properly	N/A	-	-
Hill Start Assist Control operates properly	N/A	-	-
Remote air conditioning system (if equipped) operates properly	N/A	-	-
Solar-powered ventilation system (if equipped) operates properly	N/A	-	-