

## Full Inspection Report

Inspection Date: 04-17-2026

### Inspected By

Name	Organization
Jay Medina	Beaver Toyota

### Vehicle Information Summary

VIN	Year	Make	Model	Odometer
5TDFZRAHXNS117615	2022	Toyota	Highlander	72,931

### VIN and Dealer Code Check

Question	Status	Comment	Repair/Replace
Run and print Vehicle History Report and attach	-	-	-
Run a Techstream Health Check and retain the diagnostic report in dealer file	-	-	-
Check for and perform outstanding Recalls and applicable SSCs	-	-	-

### Road Test

Question	Status	Comment	Repair/Replace
Cold engine operation performs properly	-	-	-
Throttle operates properly during cold start	-	-	-
Vehicle operates properly during warm-up conditions	-	-	-
Engine performs properly during operating temperature	-	-	-
Engine reaches normal operating	-	-	-

temperature		
Engine fan(s) operate properly	-	-
Brake pedal free play and travel within specifications	-	-
No abnormal vibrations and noises during brake applications	-	-
ABS operates properly (via Techstream Health Check)	-	-
Parking brake operates properly and within specification	-	-
Seat belt material condition	-	-
Seat belts operate properly with full extension and smooth operation	-	-
Transmission/clutch operates smoothly	-	-
Automatic transmission operates properly during cold temperature	-	-
Automatic transmission operates properly during operating temperature	-	-
Steering has normal feel in lock-to-lock turning	-	-
Steering wheel centered in straight-line driving	-	-
Vehicle tracks and drives straight on level surface	-	-
Tilt and telescopic steering mechanism operates properly	-	-
Front windshield wiper operates properly in all modes	-	-
Rear windshield wiper operates properly in all modes	-	-
Windshield washer fluid sprays properly	-	-
Wiper blades clear glass properly	-	-
Wipers return to correct position when off	-	-
Speedometer functions properly	-	-
Odometer application registers mileage in every mode	-	-
Cruise control operates properly	-	-
Heater operates properly	-	-
A/C operates properly	-	-

No abnormal noise or vibration from engine	-	-
No excessive wind or road noise	-	-
No abnormal tire vibration/steering wheel shimmy during road test	-	-
No abnormal squeaks/rattles within the interior of the vehicle	-	-

## Frame, Structure and Underbody

Question	Status	Comment	Repair/Replace
Frame/Unibody condition	-	-	-
Panel alignment and fit	-	-	-
Lower body and underbody condition	-	-	-
Suspension-related items for wear/leaks and proper performance	-	-	-
Inspect struts/shocks for leaks and wear	-	-	-
Power steering system operates properly with no leaks	-	-	-
Wheel covers secure and reasonably free of damage	-	-	-
Tires are inflated to specification and free of defects and damage	-	-	-
Minimum of 5/32" tread depth remaining across tread width	-	-	-
All four tires must be of same brand, model, size, tread design, speed and load rating	-	-	-
Brake calipers and lines operate properly with no signs of damage	-	-	-
The brake system contains all needed equipment (shim kit, pins, rattle clips, etc.)	-	-	-
Brake pad/shoe linings have a minimum thickness of 50% remaining	-	-	-
Brake rotors/drums within specifications with no abnormal grooving and discoloration	-	-	-
Exhaust system is properly secured with no leaks	-	-	-
Engine/transmission mounts operate properly with no signs of	-	-	-

wear		
Drive/axle shafts operate properly with no damage	-	-
CV joints/boots operate properly with no signs of wear	-	-
Inspect engine for fuel, oil, coolant or other fluid leaks	-	-
Inspect transmission case and pan for leaks	-	-
Differential fluid level correct with no leaks	-	-

## Emissions and State Inspection

Question	Status	Comment	Repair/Replace
Perform emissions test and/or state inspection, if required		-	-

## Under Hood

Question	Status	Comment	Repair/Replace
Drive belts and hoses free of cracks and damage		-	-
Confirm under-hood labels and decals		-	-
Air filter in good condition		-	-
Battery has no visible damage		-	-
Perform battery check with Midtronics GR8		-	-
Battery posts and cables free of corrosion and damage		-	-
Battery properly sized and secure		-	-
Charging system operating properly and within specification		-	-
Engine coolant level within specification		-	-
Coolant specific gravity to -31° Fahrenheit		-	-
Change engine oil and filter		-	-
Check for evidence of oil gel		-	-
Oil, brake, clutch, transmission, transfer case, power steering and washer fluid at proper levels		-	-

Under-hood fluids clear and uncontaminated

-

## Functional and Walkaround

Question	Status	Comment	Repair/Replace
Owner's Manual and TCUV Warranty Supplement in dealer's possession		-	-
Fuel gauge operational		-	-
Battery voltage gauge operational		-	-
Engine temperature gauge operational		-	-
Horn operates properly		-	-
Airbag(s) present with no evidence of deployment		-	-
Headlights are properly aligned		-	-
High and low beams operate properly		-	-
Tail lights operate properly		-	-
Brake lights operate properly		-	-
Side marker lights operate properly		-	-
Backup lights operate properly		-	-
License plate lights operate properly		-	-
No cracked or broken lenses of exterior lights		-	-
Instrument panel/warning lights operate properly		-	-
HVAC panel/lights operate properly		-	-
Instrument panel light dimmer operates properly		-	-
Turn signals operate properly and self-cancel		-	-
Rear-view interior mirror operates properly		-	-
Exterior mirrors' operation and condition		-	-
Remote mirror control operates properly		-	-

Glass free of cracks, stars and large chips	-	-
Window tinting clear and conforms to local requirements	-	-
Dome/courtesy lights operate with door cycles	-	-
Windows operate properly	-	-
Window locks operate properly	-	-
Power windows operate from master switch and all door switches	-	-
Audio/Cassette/CD/Aux system working properly; CD cartridge present (if equipped)	-	-
Audio speakers do not rattle at high volume and function properly	-	-
Antenna is present and functional	-	-
Clock operates properly	-	-
12v ACC power outlet operates properly	-	-
Ashtrays (if equipped) are present and operate properly	-	-
Headliner, sun visors, dash pad, upholstery, console, cup holders, trim panels and carpet are in place, in good condition and operate properly	-	-
Driver floor mat (if equipped) is appropriate floor mat for the vehicle, properly secured and not stacked on top of another floor mat	-	-
Doors open and close properly	-	-
Door locks, including child safety locks, operate properly	-	-
Remote keyless entry system and smart key system operate properly	-	-
Master key is present	-	-
Theft deterrent system operates properly	-	-
Seat adjustments and seat heater(s) operate properly	-	-
Memory seat control operates properly	-	-
Headrests function properly	-	-

Defogger indicator light operates properly	-	-
Rear defogger operates properly	-	-
Luggage compartment light operation and trim appearance	-	-
Luggage compartment is clean, free of debris, no stains	-	-
Hood and luggage compartment latches operate properly	-	-
Interior remote luggage compartment release operates properly	-	-
Emergency trunk release operates properly	-	-
Fuel door release operates properly	-	-
Spare tire's cover appearance and condition	-	-
Spare tire present	-	-
Spare tire has correct air pressure and a minimum of 5/32" tread remaining	-	-
No signs of damage to spare tire	-	-
Spare tire and storage areas are clean	-	-
Spare tire is securely fastened	-	-
Jack and tools are correct, present and secured	-	-
Acceptable aftermarket items checked	-	-
Removal of unacceptable aftermarket items	-	-

## Exterior Appearance

Question	Status	Comment	Repair/Replace
Body surface condition	-	-	-
Exterior is washed, clean and free of water spots	-	-	-
Paint is free of swirl marks and has an even, high luster	-	-	-
Paint is free of removable scratches	-	-	-
Paint is free of wax residue	-	-	-

Wheels/wheel covers are clean	-	-
Wheel wells are clean	-	-
Tires are clean and properly dressed	-	-

## Engine Compartment

Question	Status	Comment	Repair/Replace
Compartment is clean	-	-	-
Under-hood heat insulator pad is clean	-	-	-
Engine and compartment are properly dressed	-	-	-

## Interior Appearance

Question	Status	Comment	Repair/Replace
Interior is free of debris	-	-	-
Dash and vents are clean and properly dressed	-	-	-
All crevices are clean	-	-	-
Ashtrays and lighter are clean (if equipped)	-	-	-
Door jambs are clean	-	-	-
Glove box and console compartments are clean	-	-	-
Cabin air filter condition	-	-	-
Seats, carpets, floor mats (if equipped) and headliner are free of stains	-	-	-
Free of odor, including heavy fragrance	-	-	-
Glass is clean and free of streaks	-	-	-
No evidence of previous improper interior repairs	-	-	-

## Exterior Repairs

Question	Status	Comment	Repair/Replace
Body is free of all dents	-	-	-
Body is reasonably free of dings	-	-	-

Paint is reasonably free of scratches and chips

-

-

Vehicle is free of improper paint repairs or mismatched color

-

-

Glass is free of improper repairs

-

-

Bumpers are free of cuts, gouges and mismatched paint

-

-

## Interior Repairs

Question	Status	Comment	Repair/Replace
Interior leather, vinyl, plastic, carpet and fabric surfaces are free of holes, rips, tears, excessive wear or fading		-	-

## Additional Inspection Items

Question	Status	Comment	Repair/Replace
"Fade-away" dome light operates properly		-	-
Sunroof/convertible top operates properly through full range of positions		-	-
Convertible top lockout function operates properly		-	-
Radio security codes cleared		-	-
Navigation system operates properly and memory system cleared		-	-
Transfer case smoothly switches from 2WD to 4WD and back from 4WD to 2WD		-	-
Truck bed is in good condition		-	-
Truck bed-liner is in good condition and secured		-	-
Tailgate operates properly		-	-
Backup camera operates properly		-	-
Bluetooth® searches for signal		-	-
SOS (Safety Connect) light illuminates green		-	-
Lane Keep Assist operates properly		-	-
Dynamic Radar Cruise Control/Pre-Collision Systems		-	-

operate properly

Intelligent Parking Assist  
operates properly

-

-

## Hybrid Components

Question	Status	Comment	Repair/Replace
Hybrid battery		-	-
Battery control module (battery voltage sensor)		-	-
Hybrid power management control module		-	-
Electric motor/generator operates properly		-	-
ECVT operates smoothly and properly		-	-
Power inverter operates properly		-	-
Inverter coolant level		-	-
EV/Eco/Power modes operate properly		-	-
Check transaxle "park" mechanism		-	-
Multi-information display operates properly		-	-
Touch Tracer display operates properly		-	-
Hill Start Assist Control operates properly		-	-
Remote air conditioning system (if equipped) operates properly		-	-
Solar-powered ventilation system (if equipped) operates properly		-	-